
Figure 1 (Prior Art)





P. L. C. C. C. S. C. P. C. P. C. P. C. S. C. S.

R	A	М	W	Total
I ₄ =5	I ₃ =20	I ₂ =30	I ₁ =10	65
I ₅ =10	I ₄ =20	I ₃ =20	I ₂ =20	70
I ₆ =5	I ₅ =15	I ₄ =15	I ₃ =10	45
I ₇ =10	I ₆ =20	I ₅ =20	I ₄ =10	60
I ₈ =15	I ₇ =20	I ₆ =30	I ₅ =15	80

220




Figure 3

Figure 4








Figure 5

R	A	M	W	Total
I ₄ =5	I ₃ =20	I ₂ =30	I ₁ =10	65
I ₅ =10	I ₄ =20	I ₃ =20	I ₂ =20	70
I ₆ =5	I ₅ =15	I ₄ =15	I ₃ =10	45
I ₇ =10	I ₆ =20	I ₅ =20	I ₄ =10	60
I ₈ =15	I ₇ =20	I ₆ =30	I ₅ =15	80

520







The East Control of Co




Figure 8




Figure 10




Figure 11

